

December 2, 1988

TO: File

FROM: D. Wayne Hedberg *DWH*

RE: Site Inspection, Thomas J. Peck and Sons, Incorporated,
Nephi Gypsum Quarry, M/023/011, Juab County, Utah

On December 2, 1988, Division staff members Wayne Hedberg, Holland Shepherd and Scott Johnson visited the Nephi Gypsum Quarry mine site. Purpose of the inspection was to follow up on a previous directive given by the Division to the operator. The directive involved correcting a breached berm which is located immediately adjacent to a perennial drainage. The immediate area of concern had been corrected. Another smaller berm breach to the east could not be inspected due to recent snow cover. Surface drainage will now be contained on the mine site.

No activity was noted during the site inspection. There was a large front end loader present at the mine site. It was apparent that there had been recent mining activity; probably within the last 24 to 48 hours. No other environmental or health and safety issues were noted during the inspection.

jb
cc: Lowell Braxton
Minerals Team
MN2/32